

Technical Information

LRD9 series

Guided wave radar level meter




Winters Instrument (Shanghai) Co., LTD

Contents

1. Product introduction	3
1.1 Product Features	3
1.2 Safety Guide.....	3
1.3 Instrument Overview.....	4
2. Installation	6
2.1 Basic Requirements	6
2.2 Picture Description	7
2.3 Electrical connections.....	9
3. Operation and debugging	12
3.1 Debugging Method	12
3.2 Display/Debug module	13
3.3 Programming Menu Description	13
3.4 Debugging of the upper machine.....	37
3.5 HART Handheld Editor	38
4. Maintenance and repair.....	38
4.1 Meter Cleaning	38
4.2 Basic Maintenance	38
5. Schedule	39

1. Product introduction

The high frequency microwave pulse emitted by the guided wave radar propagates along the detection component (steel cable or steel rod), encounters the measured medium, and causes reflection due to the sudden change of dielectric constant, and part of the pulse energy is reflected back. Transmitted pulse and reflected pulse. The time interval is proportional to the distance of the measured medium.



1.1 Product Features

(1) Due to the use of advanced microprocessor and unique EchoDiscovery echo processing technology, guided wave radar level meter can be applied to a variety of complex conditions.

(2) A variety of process connection methods and types of detection components make the LRD9 series guided wave radar level meter suitable for various complex conditions and applications. Such as: high temperature, high pressure and small dielectric constant media.

(3) Pulse working mode, guided wave radar level meter transmission power is very low, can be installed in a variety of metal, non-metal containers, no harm to the human body and the environment.

1.2 Safety Guide

The installation personnel must be professional and technical personnel (electricians, etc.) authorized by the state. The installation process strictly follows the instructions, application specifications, laws and regulations.

Installation personnel read and understand the instructions and precautions.

If the fault cannot be repaired, the device must be disabled to prevent miscommissioning. The faulty device is identified.

When the equipment needs to be installed in hazardous areas such as explosion-proof areas, it must comply with the requirements of certificates, national and local regulations. Installation specifications, connection parameters and safety guidelines listed in the explosion-proof manual must be followed.



Warning


Misoperation can result in injury safety incidents or damage to equipment



Attention

Operational errors will result in device functionality errors

1.3 Instrument Overview

LRD901	
<p>Applications: Liquid and solid measurement, complex process conditions</p> <p>Maximum range: cable: 30m/ rod: 6m</p> <p>Accuracy: $\pm 3\text{mm}$</p> <p>Process connection: G1½A / G2A / 1½NPT</p> <p>Probe rod/cable material: stainless steel 316L</p> <p>Process temperature: (-40~150) °C</p> <p>Process pressure: (-0.1~4) MPa</p> <p>Signal output: (4~20) mA/HART</p> <p>Power source: two-wire system (DC24V) / Four-wire system (DC 24V/AC 220V)</p>	
LRD902	

Application: Highly corrosive liquid media
 Maximum range: 6m
 Accuracy: $\pm 3\text{mm}$
 Process connection: PTFE flange
 Probe rod material: stainless steel with PTFE
 PTFE rod diameter: $\phi 10\text{mm}$
 Process temperature: $(-40\sim 150)^{\circ}\text{C}$
 Process pressure: $(-0.1\sim 1.6)\text{MPa}$
 Signal output: $(4\sim 20)\text{mA/HART}$
 Power source: two-wire system (DC24V) /
 Four-wire system (DC 24V/AC 220V)



LRD903

Applications: Liquid measurement, especially small dielectric constant liquids, complex process conditions
 Maximum range: 6m
 Accuracy: $\pm 3\text{mm}$
 Process connection: G1½A, G2A
 Probe rod/cable material: stainless steel 316L/PTFE
 Coaxial outer diameter: $\phi 38\text{mm}$
 Process temperature: $(-40\sim 150)^{\circ}\text{C}$
 Process pressure: $(-0.1\sim 4)\text{MPa}$
 Signal output: $(4\sim 20)\text{mA/HART}$
 Power source: two-wire system (DC24V) /
 Four-wire system (DC24V/AC 220V)



LRD904

Applications: liquid measurement, high temperature and high pressure conditions, complex process conditions

Maximum range: cable: 30m/ bar: 6m

Accuracy: $\pm 3\text{mm}$

Process connection: G1½A/G2A/1½NPT

Probe rod/cable material: stainless steel 316L/ ceramic

Process temperature: (-40 ~ 200)°C

Process pressure: (-0.1~4) MPa

Signal output: (4 ~ 20)mA/HART

Power source: two-wire system (DC24V) /

Four-wire system (DC 24V/AC 220V)



LRD905

Applications: liquid measurement, high temperature and high pressure conditions, complex process conditions

Maximum range: cable: 30m/ bar: 6m

Accuracy: $\pm 3\text{mm}$

Process connection: G1½A /G2A/1½NPT

Probe rod/cable material: stainless steel 316L/ ceramic

Process temperature: (-200~400) °C

Process pressure: (vacuum ~40) MPa

Signal output: (4~20) mA/HART

Power source: two-wire system (DC24V) /

Four-wire system (DC 24V/AC 220V)



2. Installation


2.1 Basic Requirements

Ensure that the cable or rod does not come into contact with internal obstacles throughout the range, so installation should be as far as possible away from the tank facilities, such as: ladder, limit switch, heating equipment, bracket, etc. Care must also be taken that the cable or rod does not intersect with the feed flow.

When installing the instrument, pay attention to: the highest material level shall not enter the measurement blind area; The instrument must be kept at a

certain distance from the tank wall; The meter is installed so that the cable or rod orientation is as perpendicular as possible to the surface of the measured medium. Instruments installed in explosion-proof areas must comply with the national explosion-proof danger zone installation regulations. The intrinsically safe shell is aluminum. This type of instrument can be installed in the explosion-proof requirements of the occasion, the instrument must be grounded.


2.2 Picture Description



The reference surface for measurement is the sealing surface of the thread

- 1 Blind Zone Range (Menu 1.10)
- 2 cable lengths (Menu 1.9)
- 3 High Level Adjustment (Menu 1.2)
- 4 Low Level Adjustment (Menu 1.1)
- 5 Reference surface

Note: When using radar level meter, make sure that the material level meter cannot enter the measurement blind area.



For conical containers, the best place to install the meter is in the center of the top of the container, so that the measurement can be guaranteed to the bottom of the container.

<p>Container nozzle The length of the container nozzle is as shown below:</p>	
	<p>Try to avoid takeover installation or takeover h is as small as possible. When the nozzle is long, the medium container is small or the dielectric constant of the medium is small, the double rod type can be used.</p>
<p>Erection right or wrong</p>	
	<p>① Error: Do not install the meter above the inlet flow, the cable or rod should avoid the inlet flow. ② Correct attention: outdoor installation should be taken shade, rain prevention measures.</p>
<p>moisture-proof</p>	
	<p>For instruments installed outdoors or in damp indoor environments, as well as on cooling or heating tanks, in order to prevent moisture, the cable gland should be tightened and the cable should be bent downwards at the inlet. As shown in the diagram.</p>


2.3 Electrical connections

- Power supply voltage

Two-wire system	Standard type	(20~28)VDC
	Intrinsic safety type	(21.6~26.4)VDC
	power dissipation	Max.22.5mA
	Allow ripple	
	≤ 100Hz	$U_{ss} < 1V$
	-(100-100K) Hz	$U_{ss} < 10mV$
Four-wire system	Intrinsic safety+explosion-proof	(22.8~26.4)VDC, (198~242)VAC
two-cell	power dissipation	Max.1VA, 1W


- Mode of connection

two-wire




For HART two-wire system
 (Electronic unit selection B)
 1) Power supply and signal output


Four wires (two cells)



Wiring method: 220VAC power supply,
4... 20mA output (Electronic unit selection D)



Wiring method: 24VDC power supply,
4... 20mA output (Electronic unit selection C)



Two-wire (two-cell) : 24VDC power supply, 4... 20mA output (Electronic unit selection E)

explosion-proof connection

The explosion-proof form of this product is intrinsically safe. Explosion-proof mark: Ex ia II CT1~T6Ga. The safety type guided wave radar level meter is made of die-cast aluminum housing material, and the electronic parts are made of plastic sealing structure, so as to ensure that the sparks generated when the circuit is partially faulty will not be released. The product is suitable for continuous level measurement of combustible media below Ex ia II CT1~T6Ga explosion-proof grade. This product must be powered by a safety grid when used. FBS-2 safety grid is the associated equipment of this product, and the explosion-proof form is intrinsically safe. Explosion-proof mark: [Ex ia] IIC, supply


voltage (21.6 ~ 26.4) VDC, short circuit current is 135mA, working current (4 ~ 20) mA.

All cables should be shielded cables with a maximum length of 500m from the meter to the safety gate. Distributed capacitance $\leq 0.1\mu\text{F}/\text{km}$, distributed inductance $\leq 1\text{mH}/\text{km}$. The instrument must be grounded when installed. Do not use other associated equipment that has not been inspected for explosion protection.


FBS-2 Safety gate parameters:

Um	Uo	Io	Co	Lo
250V AV/DC	26V	135mA	100nf	1.8mH
250V AV/DC	7V	140mA	10 μf	1.8mH

Debugging software was used to debug the level meter



The level meter was debugged with HART handheld programmer



3. Operation and debugging

3.1 Debugging Method


LRD9 series guided wave radar has three debugging methods:

- 1 Display/Debug module (ViewPoint)
- 2 PC debugging software
- 3 HART handheld programmer

ViewPoint is a display debugging tool that can be plugged in, and the instrument can be debugged through the 4 buttons on ViewPoint.

The language of the debug menu is optional. After debugging, ViewPoint is generally only used for display, and the measured values can be read out very clearly through the glass window.

3.2 Display/Debug module



【  】 key

- Enter the programming state;
- Confirm the programming item;
- Confirm the parameter modification.

【  】 key

- Modify parameter values.

Shortcut key

【  】 key

displays the echo curve

【  】 key

- Select the programming item;
- Select edit parameter bits
- Parameter content is displayed.

【  】 key

- Exit the programming state;
- Back to the top menu.






3.3 Programming Menu Description





Programming submenu	
Basic setup	Basic Settings include the basic parameters of the meter: low adjustment, high adjustment, material properties, damping time, signal threshold, output mapping, scalar units, scaling, cable length setting, blind zone range, sensor label.
Display	Display content: material height, LCD contrast
diagnosis.	The contents are: measuring peak value of the instrument, measuring state, selection curve, display curve, simulation







service	Includes false echoes, current output, reset, unit of measure, language, HART mode of operation, copy sensor data, cipher, distance offset, steam correction, steam correction test, steam correction adjustment
Message	Basic instrument information, such as sensor type, serial number, production date, software version











Parameter editing method	
Character/numeric parameter programming	When the menu enters the character/number programming state, the first parameter to be edited is black, at this time, you can press ▲ key to change the bit character/number, until the required character/number, press ▼, the character bit in turn black, you can program other bits, after programming, press ← keys to confirm programming.
Optional parameter programming	Optional parameter refers to the programming item several alternative parameter items, for the user to choose, use ▲ keys to point the arrow to the required parameters, press ← keys to confirm the programming.









Programming menu description	
1 Basic Settings	<p>Basic Settings include the setting of main instrument parameters, such as range, material properties, damping time, etc. In the running state, press ← key to enter the programming state, LCD display menu.</p> <div style="border: 1px solid black; border-radius: 10px; padding: 10px; width: fit-content; margin: 10px auto;"> <p>▶ Basic setup 1</p> <p>Display</p> <p>Diagnosis.</p> <p>Advanced Settings</p> <p>Message</p> </div> <p>Note: The number in the upper right corner is the menu number</p>
1.1 Low Level Adjustment	Low adjustment is used for range Settings. Together with the high level adjustment, it determines the proportion of the linear correspondence of the current output. In the main menu, when the menu number is 1, press ← to enter





	<p>the basic Settings submenu, LCD display</p> <div data-bbox="539 255 954 506" style="border: 1px solid black; padding: 5px; margin: 10px auto; width: fit-content;"> <p>Low Level Adjustment 1.1 0 .00 % 30 .000 m (d) 1 .346 m (d)</p> </div> <p>Press  key to enter the programming low percentage. Edit the percentage value and distance value by referring to the character/number parameter programming method in the previous parameter editing method. After editing, press  keys to confirm, press  keys to give up programming.</p>
1.2 High Level Adjustment	<p>High adjustment is used for range Settings. Together with the low level adjustment, it determines the proportion of the linear correspondence of the current output. When the LCD menu number is 1.1, press  to enter the high level adjustment, LCD display.</p> <div data-bbox="539 1010 954 1261" style="border: 1px solid black; padding: 5px; margin: 10px auto; width: fit-content;"> <p>High Level Adjustment 1.2 100 .00 % 0 .000 m (d) 1 .346 m (d)</p> </div> <p>At this point, press  key to program the high adjustment.</p>
1.3 Material Properties	<p>When the LCD menu number is 1.2, press the button to enter the material property programming, LCD display. The Material Properties menu is used to select solid, liquid or microDK, thereby further determining some other properties of the material that affect the measurement.</p>









	<div data-bbox="539 215 911 434" style="border: 1px solid gray; border-radius: 10px; padding: 10px; margin-bottom: 10px;"> <p>Material properties 1.3</p> <p>▶ liquid</p> </div> <div data-bbox="549 456 920 676" style="border: 1px solid gray; border-radius: 10px; padding: 10px;"> <p>Material properties 1.3</p> <p>▶ liquid</p> <p>solid</p> <p>Micro DK</p> </div>
<p>1.3.1 Rapid level change</p>	<p>When the material properties choose liquid or solid, press  key to enter the quick change menu, LCD display</p> <div data-bbox="539 833 954 1079" style="border: 1px solid gray; border-radius: 10px; padding: 10px; margin-bottom: 10px;"> <p>Rapid level change 1.3.1</p> <p>▶ yes</p> </div> <p>Then press  key to enter the quick change menu, LCD display</p> <div data-bbox="539 1191 920 1415" style="border: 1px solid gray; border-radius: 10px; padding: 10px;"> <p>Rapid level change 1.3.1</p> <p>yes</p> <p>▶ no</p> </div>
<p>1.3.2 First wave selection</p>	<p>When the material properties choose liquid or solid, the LCD display menu is 1.3.1, use  key to select the next menu to enter the first wave selection menu, LCD display</p> <div data-bbox="539 1608 920 1832" style="border: 1px solid gray; border-radius: 10px; padding: 10px; margin-bottom: 10px;"> <p>First wave selection 1.3.2</p> <p>normal ▶</p> </div> <p>Press  button to enter the first wave selection menu, LCD display</p>




















	<div data-bbox="539 215 916 439" style="border: 1px solid black; border-radius: 10px; padding: 10px; background-color: #f0f0f0;"> <p>First wave selection 1.3.2</p> <p>normal stronger</p> <p>weaken a little stronger</p> <p> strongest</p> </div> <p>Press  to select the treatment of the first wave. There are 5 methods:</p> <p>Normal: First wave amplitude is not processed (default)</p> <p>Attenuation: The first wave amplitude is reduced by 10dB</p> <p>Slightly stronger: First wave amplitude increased by 10dB</p> <p>Strong: the first wave amplitude is increased by 20dB</p> <p>Strongest: First wave amplitude increased by 40dB</p>
<p>1.3.3 (liquid) surface fluctuation</p>	<p>When the material property is liquid and the LCD menu is 1.3.2, select the next menu with  key to enter the surface fluctuation menu and the LCD display</p> <div data-bbox="539 1021 954 1272" style="border: 1px solid black; border-radius: 10px; padding: 10px; background-color: #f0f0f0;"> <p>surface fluctuation 1.3.3</p> <p>NO </p> </div> <p>Press  keys to enter the surface fluctuation selection menu, LCD display</p> <div data-bbox="539 1379 954 1630" style="border: 1px solid black; border-radius: 10px; padding: 10px; background-color: #f0f0f0;"> <p>surface fluctuation 1.3.3</p> <p>YES</p> <p> NO</p> </div>
<p>1.3.3(solid) large pile Angle</p>	<p>When the nature of the material is liquid, the LCD menu is 1.3.2, use  key to select the next menu to enter the pile corner menu, the LCD display</p>











	 <p>Press  button to enter the first wave selection menu, LCD display</p> 
1.3.4 (liquid) foam	<p>When the LCD menu is 1.3.3, use  key to select the next menu to enter the liquid level foam menu, LCD</p>  <p>Press  button again to enter the liquid foam selection menu, LCD display</p> 
1.3.4 (solid) strong dust	<p>When the LCD menu is 1.3.3, select the next menu with  key to enter the dust strong selection menu, LCD</p>  <p>Then press  key to enter the dust strong selection menu, LCD display</p>





	
<p>1.3.5 DK Value is small</p>	<p>When the liquid crystal display 1.3.4, press  key to enter the DK value adjustment setting menu, the liquid crystal display</p>  <p>Press  key again to enter DK value adjustment menu, LCD display</p>  <p>Press  key to select "Yes" for the measurement setting of DK value hours, and the LCD display is as follows. At this time, an accurate empty height value of the empty tank needs to be manually input, which is used to judge the position of the tank bottom to reduce the reflection of the tank bottom</p> 
<p>1.3.6 (liquid) wave guide tube setting</p>	<p>When the LCD menu is 1.3.5, press  key to enter the wave guide tube setting menu, LCD display</p>











	<div data-bbox="539 210 963 465" data-label="Image"> </div> <p data-bbox="456 472 1422 562">Press  key to enter the wave guide tube measurement menu, LCD display</p> <div data-bbox="539 568 957 815" data-label="Image"> </div> <p data-bbox="456 831 1422 920">Press  key to select "Yes", press  key to enter the wave guide tube diameter setting menu, LCD display</p> <div data-bbox="539 927 957 1173" data-label="Image"> </div> <p data-bbox="456 1189 1422 1272">Note: The wave guide tube setting can only be valid if the wave guide tube is present.</p>
<p>1.3.1 Micro DK</p>	<p data-bbox="456 1279 1422 1361">When the material property is micro DK, press  key to enter the LCD display set by Micro DK</p> <div data-bbox="539 1413 957 1659" data-label="Image"> </div> <p data-bbox="456 1675 1422 2056">When the material property is micro DK, it is generally used for dielectric constant less than 1.4, when the direct echo of the medium surface is very weak, or can not be measured, and the material level height can be measured by the reflection method at the bottom of the tank, then two of the following parameters need to be entered: 1. Empty height of empty can, the value of empty height of empty can or container. 2. The real material height or the dielectric constant of the substance to be measured, the</p>










	<p>two parameters are related, enter one of them. The accuracy of the above parameters directly affects the accuracy value of the measurement results. Note: The selection of "micro DK" should be careful, and most of the measurements are inappropriate. When the "micro DK" is selected, the system determines whether to use direct echo method or bottom reflection method to obtain the measurement results according to the echo situation.</p>
1.4 Damping time	<p>When the LCD menu number is 1.4, press  key to enter the damping time setting menu, LCD display</p>  <p>Press  key to enter the parameter editing state, character/number parameter programming method to edit, press  keys to confirm</p>
1.5 Signal Threshold	<p>The Signal Threshold menu is used to set the effective echo amplitude noise tolerance. When the LCD menu number is 1.4, press  key to enter the signal threshold programming, LCD display</p>   <p>See above for optional parameter programming methods to set values. Press  to confirm the edit. Note: This parameter must be adjusted by a professional according to the echo intensity.</p>


1.6 Output Mapping	<p>The output map is used to choose between a nonlinear output map and a linear map that has been set by the host computer. When the LCD menu number is 1.5, press  key to enter the output mapping editing menu, LCD display</p>  <p>Press  key to enter the parameter selection state, use  keys to select linear or other optional mapping methods, such as linear, cone, etc., press  keys to confirm after editing.</p>
1.7 Scalar unit	<p>When linear output mapping is selected, it is used to select different display units.</p> <p>When the LCD menu number is 1.6, press  key to enter the fixed scalar unit setting menu, LCD display</p>  <p>Press  key to enter the parameter selection state, use  to select different dimensions, press  key to confirm, and further select the corresponding display unit, and then use  key to confirm.</p>
1.8 Calibration	<p>When the LCD display 1.7, press  key to enter the calibration setting menu, LCD display</p>  <p>Press  key, the parameter field is black, use  keys to set the decimal point position, use  keys to confirm, 0% of the corresponding parameter field is black, use  and  keys to set parameters, press  keys to</p>


	confirm, use the same method to set 100% of the corresponding value.
1.9 Cable Length setting	<p>In order to get the correct measurement results, it is necessary to set the measuring range of the instrument. When the menu number is displayed as 1.8, press  key to enter the range setting menu, LCD display.</p>  <p>Press  key to enter the cable length setting, refer to the character/number parameter programming method in the previous parameter editing method to edit the distance value. After editing, press  keys to confirm, press  keys to give up programming.</p>
1.10 Blind Area Range	<p>When there is a fixed obstacle near the mounting thread of the sensor surface that interferes with the measurement, and the maximum material height will not reach the obstacle, the blind zone range setting function can be used to avoid measurement errors.</p> <p>When the LCD menu number is 1.9, press  key to enter the blind zone range setting menu, LCD display</p>  <p>Press  to enter the parameter editing state, and press  to confirm after editing.</p>
1.11 Sensor Labels	When the LCD menu is 1.10, press  key to move the menu to the sensor Note menu, LCD display



	 <p>Press to enter the parameter editing state. After editing, press to confirm. This concludes the Basic Settings menu.</p>
<p>2 Display</p>	<p>This function is used for display mode programming. When the LCD displays the main menu, press key to move the arrow to the display item</p>  <p>Press key to enter the display mode programming, LCD display</p>
<p>2.1 Display Content</p>	 <p>The parameter that represents the current display content is the empty height, that is, the empty height value measured by the meter display. Press key to enter the editing state, LCD display</p>  <p>Press to move the arrow to the desired parameter, and press to confirm.</p>






<p>2.2 LCD Contrast</p>	<p>When the LCD menu number is 2.1, press  to enter the LCD contrast adjustment menu, LCD display</p>  <p>Press  to enter the adjustment state</p>  <p>Use the  key and  keys to increase or decrease the contrast, then use the OK key to confirm the adjustment and save the result</p>
<p>3 Diagnosis</p>	<p>The diagnostic function is used to test the working state of the instrument and its components and to debug the system.</p>
<p>3.1 Measuring Peak Value</p>	<p>The peak shows the empty peak value during the measurement. This parameter can be cleared by using 4.3 Reset in the service menu. When the LCD displays the main menu, press  key, move the arrow to the diagnosis item, LCD display</p>  <p>Press  key to enter, LCD display</p> 


<p>3.2 Measurement Status</p>	<p>When the LCD menu number is 3.1, press  key to enter the diagnostic measurement state and display the working status of the sensor</p> 
<p>3.3 Selection curve</p>	<p>When the LCD menu number 3.2, press  key to enter the waveform curve selection function, LCD display</p>  <p>To select other curves, press  key to enter the select curve menu, LCD display</p>  <p>Use the key to move the arrow to the curve you want to display and press  to confirm the selection.</p>
<p>3.4 Echo Curve</p>	<p>When the LCD menu number 3.3 is displayed, press the  key to display the selected curve.</p>  <p>Curve scaling function Curve scaling is used to magnify the curve in the timeline and amplitude for clearer viewing. When the LCD</p>


curve is displayed, press  key to enter the curve scaling edit menu. Liquid crystal display



Use  key to move the arrow, select the zoom direction or not zoom, press  keys to confirm.


When x axis scaling is selected, press  keys to move the starting point line to the desired position, and press  keys to confirm; Press  again to move the end point to the desired position, press  to confirm, and then the curve of the selected area will be enlarged to the full screen. Press  to exit the curve display.




Simulation function is 4... Simulation output of 20mA current. It is used to check whether the current output function of the instrument is normal, and can also be used for system debugging. When the LCD menu number is 3.4, press  key to enter the simulation state, LCD display



3.5 Simulation




Key Confirm emulation function, LCD display

























Press  key to select the current output mapping mode, press  key to confirm, enter the corresponding setting menu, complete the value setting, press  key to confirm, at this time, the current output simulation value.










Note: Description of three alternative menu items


Percentage: Output current at a given percentage

	<p>value. For example, 100% corresponds to the output of 20mA and 0% corresponds to the output of 4mA. Current: Output current according to the given current value. For example, 16.6mA corresponds to 16.6mA output. Is determined by 1.1 Low adjustment, 1.2 High Adjustment and 1.6 Output mapping)</p>
<p>4 Services</p>	<p>More specialized functions are included in the service menu for use by trained personnel. It mainly includes false echo learning, current output, reset and instrument parameter saving. When the LCD displays the main menu, press key, move the arrow to the service item, the LCD displays</p> 
<p>4.1 False Echoes</p>	<p>When a fixed obstacle interferes with the measurement, the false echo learning can be used to overcome its influence. When the main menu is displayed and the menu number is 4, press to enter the service submenu, LCD</p>  <p>Press key, LCD display</p>  <p>To update/create a false echo curve, press key, move the arrow to the required bar, press key to confirm, the LCD display please wait, the instrument to learn the false echo, complete back to the false echo learning menu.</p> <p>Note: The difference between updating false echo</p>

	<p>curve and creating new false echo curve: the false echo curve of the new false echo curve after the true echo is cleared to zero, while the false echo curve of the updated false echo curve after the true echo remains unchanged.</p>
4.2 Current Output	<p>This parameter is used to set the current output mode In the LCD menu number 4.1, press  key, LCD display</p> <div data-bbox="539 667 997 940" style="border: 1px solid gray; padding: 5px; margin: 10px 0;"> <p style="text-align: right;">Current output 4.2</p> <p>Output mode:4-20mA </p> <p>Fault mode: No change </p> <p>Minimum current:4mA </p> </div> <p>Press  key, LCD display</p> <div data-bbox="539 1008 976 1272" style="border: 1px solid gray; padding: 5px; margin: 10px 0;"> <p style="text-align: right;">Current output 4.2</p> <p> Output mode</p> <p>Fault mode</p> <p>Minimum current</p> </div>
Output mode	<p>Output Mode Select 4-20mA or 20-4mA output mode. 4-20mA indicates that low material level corresponds to 4mA, high material level corresponds to 20mA; 20-4mA indicates that the low material level corresponds to 20mA, and the high material level corresponds to 4mA. In the LCD current output menu 4.2, press  key, move the arrow to the output mode, press  key to confirm the LCD display</p> <div data-bbox="539 1646 989 1915" style="border: 1px solid gray; padding: 5px; margin: 10px 0;"> <p style="text-align: right;">Output mode 4.2</p> <p> 4 – 20 mA</p> <p>20 – 4 mA</p> </div> <p>Press  to select the desired Settings, and press  to confirm the selection.</p>

Failure mode	<p>Failure mode is used to select 20.5mA or 22mA without changing the output current when there is a fault alarm. In the LCD current output menu 4.2, press  key, move the arrow to fault mode, press  key to confirm the LCD display</p> <div data-bbox="539 439 979 701" style="border: 1px solid gray; padding: 5px; margin: 10px auto; width: fit-content;"> <p style="text-align: right;">Output mode 4.2</p> <p> No change</p> <p>20.5mA</p> <p>22.0mA</p> <p>4.0mA</p> </div> <p>Press  to select the desired Settings, and press  to confirm the selection.</p>
Minimum current	<p>Minimum current The minimum output current is 4mA or 3.9mA.</p> <p>In the LCD current output menu 4.2, press  key, move the arrow to the minimum current, press  key to confirm the LCD display</p> <div data-bbox="547 1037 1003 1308" style="border: 1px solid gray; padding: 5px; margin: 10px auto; width: fit-content;"> <p style="text-align: right;">Minimum current 4.2</p> <p> 3.9mA</p> <p>4mA</p> </div> <p>Press  to select the desired Settings, and press  to confirm the selection.</p>
4.3 Resetting	<p>Reset function Resets instrument parameters. There are four reset functions: basic Settings, factory Settings, and peak measurement. The basic setting is to restore the parameters in the basic setting of the instrument to the default setting of the factory; Factory Settings Restore all instrument parameters to factory default Settings; Measurement peak reset is to reset the measurement peak in the diagnosis. When the liquid crystal display current output (menu number 4.2), press  key to enter the reset function, the liquid crystal display</p>


	 <p>Press  to enter the reset selection menu, and select the corresponding reset function item as required.</p>
<p>4.4 Measurement Unit</p>	<p>The unit of measurement provides the user with the choice of using metric or imperial measurement. When the LCD reset menu (menu number 4.3), press  key to enter the measurement unit setting menu, LCD display</p>  <p>Press  to enter the menu of measurement unit selection. You can select the corresponding measurement unit according to your needs.</p>
<p>4.5 Language</p>	<p>Language provides users with two language options: Chinese and English. When the LCD display measuring unit (menu number 4.4), press  key to enter the language setting function, LCD display</p>  <p>Press  to enter the language selection menu and select the desired language.</p>
<p>4.6 HART working mode</p>	<p>When two or more instruments are connected to the upper computer using HART communication, this function is required to set the instrument to multi-point operation mode. When the LCD displays the language menu (menu number 4.5), press  key to enter the HART working mode menu, LCD display</p>




HART Working mode 4.6

Standard

Address 0

Press  key to enter the HART mode setting interface, LCD display

If the HART working mode is selected as multi-point, the display is as follows:




HART Working mode 4.6

Address

Power source 4mA

The address can be changed from 1 to 15. Working power supplies are available in two 4mA and 8mA options.




Press  key to enter the HART mode setting interface, LCD display




HART Working mode 4.6

Standard

 Multipoint

Select standard or multipoint mode with  key. When standard mode is selected, the local address is specified as 0; If you select multi-point mode, press  keys to enter the address setting menu, and set the address to 1-15. After editing, press  keys to confirm.





HART Working mode 4.6



Standard

Address 0


4.7 Copying Sensor Data


To copy sensor data, there are two submenus: Copy from Sensor and Copy to sensor. This function is used to protect the instrument parameters. When the technician has set the instrument parameters according to the working environmental conditions, the set parameters can be saved using the copy from the sensor function, and in case the instrument parameters are accidentally modified, it can be copied to the sensor to restore it. When the LCD display HART working mode (menu number 4.6), press  key to enter the copy sensor data function, LCD display




With  key, select the desired menu, press  keys to confirm the selection and perform the function

4.8 Password








The password is used to protect the instrument parameters. After the password function is enabled, you need to enter the password when changing any instrument parameter. Once you enter the correct password, the password protection function is disabled and the instrument parameter can be modified. When the LCD copy sensor data menu (menu number 4.7), press  key to enter the password function, the LCD display







Press  to enable the password function and set or disable the password function



The distance offset setting is used to modify the measurement error of the instrument as the difference


















	<p>between the actual empty height value and the displayed empty height value. When the LCD display number menu (menu number 4.8) is displayed, press  key to enter the distance offset menu setting</p> <p>Press  key to set the distance offset</p>
<p>4.10 Steam correction</p>	<p>Steam correction function: It is specially used in guided wave radar to measure high temperature water vapor (general temperature greater than 150°C) under the working condition, because high temperature water vapor will affect the propagation speed of electromagnetic wave and then produce measurement deviation, so the measurement results need to be corrected, the function of this menu is to open the steam correction function. When the LCD display distance deviation (menu number 4.9), press  key to enter the steam correction menu, the LCD display is as follows:</p> <div data-bbox="539 1010 948 1256" data-label="Image">  </div> <p>With  key, select 'Yes' and 'No' to turn on the steam correction function, press  keys to confirm the selection and perform the function. After steam correction 'Yes' is selected, the function of automatic compensation and correction of high temperature water level at different temperatures can be realized by cooperating with the 4.11 menu.</p>
<p>4.11 Steam correction test</p>	<p>The steam correction test function is used in conjunction with the steam correction (menu 4.10). When the liquid crystal displays the steam correction (menu No. 4.10), press the button to enter the steam correction test menu, and the liquid crystal displays as follows:</p> <div data-bbox="533 1794 884 2002" data-label="Image">  </div> <p>The values in the first row are required to store the</p>

	<p>steam correction parameters in advance,</p> <p>The second line of data is the radar vapor correction parameter obtained from the current measurement. Press  key to store the current vapor correction parameter.</p> <p>The realization of the steam correction function is to manually store the value of this steam correction parameter when the water temperature is low (generally less than 100 ° C). When the temperature rises, this parameter will change with the influence of water vapor, so as to use this parameter to achieve the purpose of correcting the water level measurement, therefore, pay special attention to the low temperature storage of the "steam correction parameter" after the radar installation, when the temperature rises, do not store this parameter, otherwise it can not achieve the purpose of correction.</p>
<p>5 Messages</p>	<p>The information menu includes basic information about the production of the instrument, such as product serial number, production date, software version number, etc. When the LCD displays the main menu, press  key, move the arrow to the information item, the LCD displays</p> <div data-bbox="539 1077 992 1348" style="border: 1px solid gray; padding: 10px; margin: 10px auto; width: fit-content;"> <p style="text-align: right;">Basic Settings 5</p> <p style="text-align: center;">Display</p> <p style="text-align: center;">Diagnosis</p> <p style="text-align: center;">Service</p> <p style="text-align: center;">▶ Messag</p> </div> <p>Press  key to enter the information display function, LCD display</p> <div data-bbox="539 1496 1015 1783" style="border: 1px solid gray; padding: 10px; margin: 10px auto; width: fit-content;"> <p style="text-align: right;">Sensor type 5.1</p> <p style="text-align: center;">GDGW 5 1</p> <p style="text-align: center;">Serial number</p> <p style="text-align: center;">223456</p> </div> <p>Press  key, LCD display</p>

Production date	5.2
2013 - 01 - 01	
Software version	
13.03.28	

Method 1:

Example 1: The echo curve is displayed as follows:


1. Press  to enter the programming state, and the LCD screen displays the main menu of programming;
2. Select the submenu: Use  keys to point the arrow to the diagnostic submenu 3, and 3 is displayed in the upper right corner of the display.
3. Press  to confirm. The diagnostic submenu 3.1 displays the measurement peak values: minimum and maximum empty height.
4. Press the  key to enter the next programming item, showing the measurement form 3.2: measurement reliability, sensor status, sensor temperature;
5. Press the  key again to enter the Select Curve submenu 3.3. If the parameter item of this menu is "Echo curve", go to the eighth item below;
6. Press  to enter the parameter selection menu.
7. Use the  key to move the arrow and select "Echo Curve"; Press  key to confirm;
8. Press  to display echo curve 3.4;
9. Press  to enter the curve scaling menu;
10. Press  to select X-axis scaling and press  key to confirm;
11. Press  to move the starting point line to the desired position, and press  to confirm;
12. Press  to move the end point line to the desired position, press  to confirm, then the curve of the selected area will be enlarged to the full screen;
13. Press  keys continuously; Until it returns to the running state.

Method two:

In the main interface, press  key directly to display the shortcut of echo curve.


3.4 Debugging of the upper machine

Connect to the upper machine through HART




- 1: RS232 interface /USB interface; 2: LRD9 series;
3: HART adapter for COMWAY converter; 4:250 ohm resistance; 5: COMWAY converter

Connect to the upper machine through I²C



- 1: RS232 interface /USB interface; 2: LRD9 series;
3: I²C adapter for COMWAY converter; 4: COMWAY converter

3.5 HART Handheld Editor



4. Maintenance and repair


4.1 Meter Cleaning


When cleaning the instrument case, attention should be paid to the use of cleaning tools to protect the surface of the housing and the sealing ring from damage. When the sensor is attached, wipe it with a soft cloth as much as possible and avoid using sharp objects or hard objects to clean the sensor surface.

4.2 Basic Maintenance

The meter has a modular design and can be repaired according to 06 fault records or the module can be replaced. After replacing a module, reset the system initialization parameters. Other location faults or technical problems can be contacted by the company.

5. Schedule







Excellence Since 1953

Winters Instruments(Shanghai) Inc.

Tel: 021-61042610

Mail: rzhang@winters.com

Web: www.cn-winters.com

Address: Room 203, Block 8, Guiguo Park, No. 471 Guiping Road,
Shanghai